

# Sensor Deck Mounted Tap / Large

TSL.960

The TSL.960 is a stainless steel deck mounted sensor tap, available in a variety of coloured finishes, with a sleek and minimalist design.

Finish	Codes	LRV*
Satin	TSL.960.CS	51
<ul><li>Black</li></ul>	TSL.960.BK	3
<ul><li>Brass</li></ul>	TSL.960.BR	40
<ul><li>Copper</li></ul>	TSL.960.CP	19
Chrome	TSL.960.C	58

Light Reflectance Value\*











UK: +44 (O) 161 482 7000 www.thesplashlab.co.uk

info.uk@thesplashlab.com Making the ordinary, **extraordinary** 

Weight	1.5kg	
Material	AISI 304 Stainless Steel	
Min/Max pressure	0.5 - 7.5 bar	
Flow Rate	3.8 litres/minute; also available - 1.31/min spray, 1.891/min spray	
Aerator	Cascade flow	
Coating Type	PVD (colours only)	
Max hot water temperature	60°C	
Temperature control	Internal mixer cartridge; not thermostatic	
Power Supply (Battery)	6V CR-P2 Lithium Battery	
Power Supply (Mains)	100-240V; 1.5A; 50-60Hz PSU.	
Output (Max)	6V; 6W max	
Power Consumption	< 80μΑ	
Solenoid Valve	6V	
Water Ingress (PSU)	IP67	
Cable Lengths	Connection to sensor cable - 400mm Connection to fused supply - 1.5m	
Sensor Type	Infra red	
Pre-set sensor range	120mm	
Maximum sensor range	25Omm	
Comfort Delay	2 seconds	
Security Time-out	30 seconds	
Operating Temperature	O to 50°C	
Response Time (max)	< 300ms	
Installation requirements		
Countertop Cut-out size	ø 35mm	
Maximum Countertop thickness	50mm	
	50mm	
Plumbing Connection	50mm 1/2" BSP female connection required to solenoid valve	
Plumbing Connection  Power Supply		
	1/2" BSP female connection required to solenoid valve  3amp fused spur to be connected to IP68 transformer supplied; low voltage push fit connector to tap. For more reliable operation, it is not recommended that sensor taps are connected to an occupancy circuit. All connections must be in accord with the	
Power Supply	1/2" BSP female connection required to solenoid valve  3amp fused spur to be connected to IP68 transformer supplied; low voltage push fit connector to tap. For more reliable operation, it is not recommended that sensor taps are connected to an occupancy circuit. All connections must be in accord with the current local regulations in force.  Solenoid/isolation valves must be accessible for initial installation & commissioning	
Power Supply  Access Requirements	3amp fused spur to be connected to IP68 transformer supplied; low voltage push fit connector to tap. For more reliable operation, it is not recommended that sensor taps are connected to an occupancy circuit. All connections must be in accord with the current local regulations in force.  Solenoid/isolation valves must be accessible for initial installation & commissioning and for ongoing/routine maintenance.  Avoid installing the sensor tap directly opposite other sensor taps, soap dispensers, infrared devices or reflective surfaces.  Careful consideration should be made when choosing the positioning of lighting and other reflective surfaces which may affect sensor performance.  O.5 Bar is the recommended minimum pressure for the taps to operate effectively. 7.5 Bar is the maximum pressure for commissioning and is NOT recommended for general use.  Gravity-fed systems may require a booster pump to achieve the optimal operating pressure. All pipework must be thoroughly cleaned and clear of any debris before	
Power Supply  Access Requirements  Washroom Layout	3amp fused spur to be connected to IP68 transformer supplied; low voltage push fit connector to tap. For more reliable operation, it is not recommended that sensor taps are connected to an occupancy circuit. All connections must be in accord with the current local regulations in force.  Solenoid/isolation valves must be accessible for initial installation & commissioning and for ongoing/routine maintenance.  Avoid installing the sensor tap directly opposite other sensor taps, soap dispensers, infrared devices or reflective surfaces.  Careful consideration should be made when choosing the positioning of lighting and other reflective surfaces which may affect sensor performance.  O.5 Bar is the recommended minimum pressure for the taps to operate effectively. 7.5 Bar is the maximum pressure for commissioning and is NOT recommended for general use.  Gravity-fed systems may require a booster pump to achieve the optimal operating	
Power Supply  Access Requirements  Washroom Layout  Water Supply	3amp fused spur to be connected to IP68 transformer supplied; low voltage push fit connector to tap. For more reliable operation, it is not recommended that sensor taps are connected to an occupancy circuit. All connections must be in accord with the current local regulations in force.  Solenoid/isolation valves must be accessible for initial installation & commissioning and for ongoing/routine maintenance.  Avoid installing the sensor tap directly opposite other sensor taps, soap dispensers, infrared devices or reflective surfaces.  Careful consideration should be made when choosing the positioning of lighting and other reflective surfaces which may affect sensor performance.  O.5 Bar is the recommended minimum pressure for the taps to operate effectively. 7.5 Bar is the maximum pressure for commissioning and is NOT recommended for general use.  Gravity-fed systems may require a booster pump to achieve the optimal operating pressure. All pipework must be thoroughly cleaned and clear of any debris before	
Power Supply  Access Requirements  Washroom Layout  Water Supply  Compliance & certificates	3amp fused spur to be connected to IP68 transformer supplied; low voltage push fit connector to tap. For more reliable operation, it is not recommended that sensor taps are connected to an occupancy circuit. All connections must be in accord with the current local regulations in force.  Solenoid/isolation valves must be accessible for initial installation & commissioning and for ongoing/routine maintenance.  Avoid installing the sensor tap directly opposite other sensor taps, soap dispensers, infrared devices or reflective surfaces.  Careful consideration should be made when choosing the positioning of lighting and other reflective surfaces which may affect sensor performance.  O.5 Bar is the recommended minimum pressure for the taps to operate effectively. 7.5 Bar is the maximum pressure for commissioning and is NOT recommended for general use.  Gravity-fed systems may require a booster pump to achieve the optimal operating pressure. All pipework must be thoroughly cleaned and clear of any debris before connecting the tap.	

UK: +44 (0) 161 482 7000 www.thesplashlab.co.uk info.uk@thesplashlab.com Making the ordinary, **extraordinary** 

### Included

Sensor Deck Mounted Tap / Large

Body

Solenoid valve cable

Solenoid valve assembly

Power supply

Hex wrench

Battery

Battery holder

Flow regulator

Filter

Aerator

Fixing nut


Sealing washer

Anti rotation plate

Aerator key

#### Warranty

1 Year limited - unlimited digital support



## Spare parts

If a situation arises where you require replacement components outside of a maintenance contract, there may be provision to obtain spare parts. Providing the components are under warranty and the parts have become non-functioning during normal use within their assumed usable life, they may be replaced. Should a replacement mains power supply be required it is imperative that an identical type is used. Contact **The Splash Lab** for further information.

Part	Codes
Long Range IR Sensor	TSLP.260045
Solenoid Connector Cable	TSLP:120032

## Related products



Wall Mounted Cylindrical Pump Soap Dispenser TSL.938



Sensor Deck Mounted Soap Dispenser TSL.420